

Regarding Approval RA23022X
NW 15-42-16 W4M

Catch Basin Liner Inspection Statement

The purpose of this statement is to outline the catch basin liner inspection requirement in Approval RA23022X. Operating condition 4 of Approval RA23022X reads:

“A qualified individual shall visually inspect the condition of the synthetic liners in catch basins 1 and 2, according to liner monitoring requirements prescribed by the NRCB in writing. The NRCB may, based on inspection results and at its discretion, revise those requirements from time to time, in writing.”

In Board Decision 2025-02, the NRCB's Board varied Approval RA23022 and Approval Amendment RA23022A, by requiring additional conditions, including ongoing liner inspections for the two catch basins.

Based on this decision, the catch basin liner inspection for both of catch basin 1 and catch basin 2 at this site should be as follows:

Monitoring frequency

Every three years, starting in 2028, with results submitted to the NRCB by November 30 in 2028, 2031, and 2034.

Frequency will be reassessed in 2035.

Inspection parameters

Date the inspection took place
Overall condition of the liner, including description of signs of damage or wear
If any repairs are necessary
If any signs of uplifting of the liner are present

The synthetic liner must be inspected by a qualified individual.

These monitoring requirements become effective on the date of this statement and supersede any previously issued catch basin liner inspection monitoring requirements at this facility.

August 20, 2025

(Original signed)

Lynn Stone
Approval Officer